

National Transportation Safety Board Aviation Accident Final Report

Location: MESA, AZ Accident Number: LAX85LA257

Date & Time: 05/13/1985, 1943 MST Registration: N4661V

Aircraft: CESSNA T303 Aircraft Damage: Destroyed

Defining Event: Injuries: 1 Serious

Flight Conducted Under: Part 91: General Aviation - Positioning

Analysis

PLT TOOK OFF FROM SCOTTSDALE AT 1934 MST FOR A 13 NM FLT TO REPOSITION THE ACFT TO HOME BASE. WITHIN MINUTES THE PLT ADVISED ATC THAT HE WAS 6 MI OUT WITH MINIMUM FUEL AND REQUESTED NO DELAY. HE THEN ASKED FOR CLEARANCE TO RWY 22R AND WAS CLEARED TO LAND ON RWY 22R, AT 1943 MST THE PLT ADVISED THE TWR THAT HE WAS NOT GOING TO MAKE THE RWY. BOTH ENGS HAD STOPPED DUE TO FUEL EXHAUSTION AND THE PLT MADE A FORCED LANDING 1/4 MILE FROM THE APCH END OF RWY 22R IN A LEVEL DIRT AREA. THE PLT REPORTED THE ACFT CONTAINED 120 LBS OF FUEL UPON DEPARTURE FROM SCOTTSDALE AND NO LOW FUEL WARNING WAS RECEIVED. THE PLT'S OPERATING HANDBOOK STATES THE LOW FUEL WARNING LIGHT SHOULD ILLUMINATE WHEN THERE IS LESS THAN 60 GALLONS OF FUEL IN EITHER TANK OR WHEN THERE IS LESS THAN 120 GALLONS TOTAL FUEL ON BOARD. THE MANUAL ALSO STATED THE ACFT BURNS 170 GPH AT 70 PERCENT POWER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

1. (C) PREFLIGHT PLANNING/PREPARATION - IMPROPER - PILOT IN COMMAND

2. (F) FLUID, FUEL - EXHAUSTION

3. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

4. (F) TERRAIN CONDITION - OPEN FIELD

5. (F) LIGHT CONDITION - DUSK

Page 2 of 5 LAX85LA257

Factual Information

Pilot Information

Certificate:	Airline Transport	Age:	35, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	03/25/1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	2665 hours (Total, all aircraft), 32 hours (Total, this make and model), 45 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4661V
Model/Series:	T303 T303	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	T30300276
Landing Gear Type:	Retractable -	Seats:	6
Date/Type of Last Inspection:	12/01/1984, Annual	Certified Max Gross Wt.:	5150 lbs
Time Since Last Inspection:	59 Hours	Engines:	2 Reciprocating
Airframe Total Time:	59 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	TSIO-520-AE
Registered Owner:	SUPERSTITION AIR SERVICE	Rated Power:	250 hp
Operator:	SUPERSTITION AIR SERVICE	Operating Certificate(s) Held:	

Page 3 of 5 LAX85LA257

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Dusk
Observation Facility, Elevation:	FFZ, 1393 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1945 MST	Direction from Accident Site:	220°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	40 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SCOTTSDALE, AZ (SDL)	Type of Flight Plan Filed:	None
Destination:	MESA, AZ (FFZ)	Type of Clearance:	
Departure Time:	1934 MST	Type of Airspace:	

Airport Information

Airport:	FALCON FLD. (FFZ)	Runway Surface Type:
Airport Elevation:	1393 ft	Runway Surface Condition:
Runway Used:	22R	IFR Approach:
Runway Length/Width:	3800 ft / 75 ft	VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ALAN A CRAWFORD	Report Date:
Additional Participating Persons:	OSCAR CULP; FHOENIX, AZ	
Publish Date:	08/03/2011	
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .	

Page 4 of 5 LAX85LA257

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 LAX85LA257