

# National Transportation Safety Board Aviation Accident Final Report

| Location:               | BLOOMINGTON, IN                      | Accident Number: | DCA86AA001                      |
|-------------------------|--------------------------------------|------------------|---------------------------------|
| Date & Time:            | 10/19/1985, 1535 EDT                 | Registration:    | N923RC                          |
| Aircraft:               | VICKERS VISCOUNT VC-810              | Aircraft Damage: | Destroyed                       |
| Defining Event:         |                                      | Injuries:        | 1 Serious, 17 Minor,<br>10 None |
| Flight Conducted Under: | Part 91: General Aviation - Business |                  |                                 |

### Analysis

DRG AN ILS TO RWY 35, THE APCH WAS NORMAL UNTIL THE ACFT WAS APRX 100' ABV THE DECISION HEIGHT, EXCEPT THERE WAS CONDENSATION ON THE WINDSHIELD. TOUCHDOWN WAS HARD. A WITNESS SAID THE ACFT LNDD APRX 1/3 OF THE WAY DOWN THE 5200' RWY. AFTER LNDG, WITH THE PROPS IN 'GROUND FINE,' BRAKING ACTION WAS INEFFECTIVE ON THE WET RWY. THE ACFT WAS NOT EOUIPPED WITH AN ANTI-SKID BRAKING SYS. SUBSEQUENTLY, THE ACFT CONTD OFF THE RWY & WENT DOWN AN EMBANKMENT INTO A FIELD.SCRUB MARKS ON THE RWY & REVERTED RUBBER ON THE TIRES INDICATED THE ACFT WAS HYDROPLANING. ACCORDING TO THE FLT MANUAL, 4500' (PLUS A 10% FACTOR FOR NO ANTI-SKID) WOULD HAVE BEEN REQUIRED TO STOP ON A DRY RWY IN THE PREVAILING WX CONDS, WHICH INCLUDED A SLIGHT TAILWIND. TWO PAX, ACTING AS FLT ATTENDANTS (F/A'S), ASSISTED THE OTHER PAX IN EVACUATING. AN INVESTIGATION REVEALED THE F/A'S WERE NOT PROPERLY TRAINED; THE PAX WERE NOT COMPLETELY BRIEFED BEFORE THE FLT; & THE PAX BRIEFING CARDS WERE INADEQUATE. THE ACFT WAS ON A BUSINESS FLT TO TRANSPORT AN ENTERTAINMENT TROUPE.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### Findings

Occurrence #1: OVERRUN Phase of Operation: LANDING - ROLL

Findings

- 1. (F) WEATHER CONDITION TAILWIND
- 2. (F) WEATHER CONDITION FOG
- 3. (F) WEATHER CONDITION RAIN
- 4. (F) WINDOW, FLIGHT COMPARTMENT WINDOW/WINDSHIELD DIRTY(FOGGY)
- 5. (C) PROPER TOUCHDOWN POINT EXCEEDED PILOT IN COMMAND
- 6. (C) VISUAL/AURAL PERCEPTION PILOT IN COMMAND
- 7. (C) IN-FLIGHT PLANNING/DECISION IMPROPER PILOT IN COMMAND
- 8. (C) MISSED APPROACH NOT PERFORMED PILOT IN COMMAND
- 9. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION WET
- 10. (F) AIRCRAFT PERFORMANCE, HYDROPLANING CONDITION WATER

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Findings

11. (F) TERRAIN CONDITION - ROUGH/UNEVEN 12. (F) TERRAIN CONDITION - DOWNHILL

-----

Occurrence #3: MISCELLANEOUS/OTHER Phase of Operation: OTHER

Findings

13. (F) PASSENGER BRIEFING - INADEQUATE - FLIGHT ATTENDANT

- 14. (F) INADEQUATE TRAINING (EMERGENCY PROCEDURE(S)) FLIGHT ATTENDANT
- 15. (F) INFORMATION UNCLEAR COMPANY/OPERATOR MANAGEMENT

## **Factual Information**

#### **Pilot Information**

| Certificate:              | Airline Transport                                | Age:                                  | 67, Male                      |
|---------------------------|--|---------------------------------------|-------------------------------|
| Airplane Rating(s):       | Multi-engine Land; Single-engine<br>Land         | Seat Occupied:                        | Left                          |
| Other Aircraft Rating(s): |  | Restraint Used:                       | Seatbelt, Shoulder<br>harness |
| Instrument Rating(s):     | Airplane   | Second Pilot Present:                 | Yes                           |
| Instructor Rating(s):     | Airplane Multi-engine; Airplane<br>Single-engine | Toxicology Performed:                 | No                            |
| Medical Certification:    | Class 2 Valid Medicalw/<br>waivers/lim.          | Last FAA Medical Exam:                | 10/08/1985                    |
| Occupational Pilot:       |  | Last Flight Review or Equivalent:     |                               |
| Flight Time:              | 27000 hours (Total, all aircraft), 600           | 00 hours (Total, this make and model) |                               |

### Aircraft and Owner/Operator Information

| Aircraft Make:                | VICKERS  | Registration:                     | N923RC       |
|-------------------------------|--|-----------------------------------|--------------|
| Model/Series:                 | VISCOUNT VC-810 VISCOUNT<br>V                          | Aircraft Category:                | Airplane     |
| Year of Manufacture:          |  | Amateur Built:                    | No           |
| Airworthiness Certificate:    | Transport  | Serial Number:                    | 320          |
| Landing Gear Type:            | Retractable - Tricycle                                 | Seats:                            | 34           |
| Date/Type of Last Inspection: | 10/14/1985, Continuous<br>Airworthiness                | Certified Max Gross Wt.:          | 72500 lbs    |
| Time Since Last Inspection:   | 4 Hours  | Engines:                          | 4 Turbo Prop |
| Airframe Total Time:          | 11707 Hours  | Engine Manufacturer:              | Rolls-Royce  |
| ELT:                          | Installed, activated, did not aid in locating accident | Engine Model/Series:              | DART 525     |
| Registered Owner:             | RAY CHARLES ENTERPRISES                                | Rated Power:                      |              |
| Operator:                     | RAY CHARLES ENTERPRISES                                | Operating Certificate(s)<br>Held: | None         |

### Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Instrument Conditions             | Condition of Light:                     | Day              |
|----------------------------------|-----------------------------------|---|------------------|
| Observation Facility, Elevation: | BMG, 847 ft msl                   | Distance from Accident Site:            | 0 Nautical Miles |
| Observation Time:                | 2005 CDT                          | Direction from Accident Site:           | 350°             |
| Lowest Cloud Condition:          | Partial Obscuration / 0 ft<br>agl | Visibility                              | 1 Miles          |
| Lowest Ceiling:                  | Broken / 600 ft agl               | Visibility (RVR):                       | 0 ft             |
| Wind Speed/Gusts:                | 5 knots /                         | Turbulence Type<br>Forecast/Actual:     | /                |
| Wind Direction:                  | 230°                              | Turbulence Severity<br>Forecast/Actual: | /                |
| Altimeter Setting:               | 30 inches Hg                      | Temperature/Dew Point:                  | 19°C / 18°C      |
| Precipitation and Obscuration:   |                                   |   |                  |
| Departure Point:                 | LEXINGTON, KY (LEX)               | Type of Flight Plan Filed:              | IFR              |
| Destination:                     |                                   | Type of Clearance:                      | IFR              |
| Departure Time:                  | 1430 CDT                          | Type of Airspace:                       | Class E          |
|                                  |                                   |   |                  |

#### **Airport Information**

| Airport:             | MONROE COUNTY (BMG) | Runway Surface Type:      | Asphalt |
|----------------------|---------------------|---------------------------|---------|
| Airport Elevation:   | 847 ft              | Runway Surface Condition: | Wet     |
| Runway Used:         | 35                  | IFR Approach:             | ILS     |
| Runway Length/Width: | 5200 ft / 150 ft    | VFR Approach/Landing:     | None    |

### Wreckage and Impact Information

| Crew Injuries:      | 1 Serious, 1 Minor           | Aircraft Damage:     | Destroyed |
|---------------------|------------------------------|----------------------|-----------|
| Passenger Injuries: | 16 Minor, 10 None            | Aircraft Fire:       | None      |
| Ground Injuries:    | N/A                          | Aircraft Explosion:  | None      |
| Total Injuries:     | 1 Serious, 17 Minor, 10 None | Latitude, Longitude: |           |

#### Administrative Information

| Investigator In Charge (IIC):     | G   | M DAIL | Report Date: |
|-----------------------------------|---|--------|--------------|
| Additional Participating Persons: |   |        |              |
| Publish Date:                     |   |        |              |
| Investigation Docket:             | NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <u>pubing@ntsb.gov</u> , or at 800-877-6799. Dockets released after this date are available at <u>http://dms.ntsb.gov/pubdms/</u> . |        |              |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <u>here</u>.