

National Transportation Safety Board Aviation Accident Final Report

Location: WILMINGTON, DE Accident Number: NYC83FA214

Date & Time: 08/17/1983, 0724 EDT Registration: N108PA

Aircraft: GATES LEARJET 25B Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled

Analysis

AFTER LIFT-OFF A FLOCK OF BIRDS APPROACHED FROM LEFT TO RIGHT AT ABOUT 400 FT. THE PLT MANEUVERED THE ACFT BEHIND & ABOVE THE BIRDS IN AN ATTEMPT TO AVOID THEM. BOTH ENGS FLAMED OUT & THE ACFT MDE A FORCED LANDING ON A ROAD. GROUND WITNESSES DESCRIBED THE CLIMBOUT AS '...VERY STEEP...' & '...A STEEP ANGLE, BETWEEN 40 AND 45 DEGREES.' THERE WAS SOME BIRD RESIDUE ON THE ENGS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (F) MANEUVER - PERFORMED - PILOT IN COMMAND

2. (C) AIRCRAFT PERFORMANCE, CLIMB CAPABILITY - EXCEEDED

3. (C) AIRCRAFT HANDLING - IMPROPER - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Findings

4. (F) AIRCRAFT PERFORMANCE, TWO OR MORE ENGINES - INOPERATIVE

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Findings

5. OBJECT - BIRD(S)

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #5: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

6. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 5 NYC83FA214

Factual Information

Pilot Information

Certificate:	Airline Transport	Age:	29, Male
Airplane Rating(s):	Multi-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	07/11/1983
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	4304 hours (Total, all aircraft), 1420 hours (Total, this make and model), 4304 hours (Pilot In Command, all aircraft), 130 hours (Last 90 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	GATES LEARJET	Registration:	N108PA
Model/Series:	25B 25B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Transport	Serial Number:	195
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	07/28/1983, Continuous Airworthiness	Certified Max Gross Wt.:	15000 lbs
Time Since Last Inspection:	38 Hours	Engines:	2 Turbo Jet
Airframe Total Time:	4758 Hours	Engine Manufacturer:	GE
ELT:	Not installed	Engine Model/Series:	C5610-6
Registered Owner:	I.J.A., INC.	Rated Power:	2950 lbs
Operator:	NORTHEAST JET CO.	Operating Certificate(s) Held:	On-demand Air Taxi (135)

Page 3 of 5 NYC83FA214

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	ILG, 80 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	0651	Direction from Accident Site:	360°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	68 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16°C / -18°C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	IFR
Destination:	DANVILLE, VA (DAN)	Type of Clearance:	IFR
Departure Time:	0716	Type of Airspace:	

Airport Information

Airport:	GREATER WILMINGTON (ILG)	Runway Surface Type:	Asphalt
Airport Elevation:	80 ft	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	7165 ft / 150 ft	VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	MICHEAL	KUZENKO	Report Date:
Additional Participating Persons:			
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .		

Page 4 of 5 NYC83FA214

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 NYC83FA214