

National Transportation Safety Board Aviation Accident Final Report

Location: GOLOVIN, AK Accident Number: ANC85FA085

Date & Time: 05/16/1985, 1345 AKD Registration: N73635

Aircraft: CESSNA C-207A Aircraft Damage: Substantial

Defining Event: Injuries: 2 Fatal, 3 Serious

Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled

Analysis

ACCORDING TO THE PILOT-IN-COMMAND, HE WAS ATTEMPTING TO FLY THROUGH A MOUNTAIN SADDLE. AS HE TURNED TOWARDS THE MOUNTAIN AND BEGAN HIS CLIMB THE WEATHER DETERIORATED RAPIDLY WITH CEILINGS ZERO, VISIBILITY ZERO AND SEVERE TURBULENCE. THE AIRPLANE STRUCK THE SIDE OF A 1707 FOOT HIGH MOUNTAIN AT THE 1590 FOOT LEVEL ON A MAGNETIC HEADING OF 015 DEGREES. THE PILOT-IN-COMMAND STATED THAT JUST PRIOR TO IMPACT HE COULD NOT SEE ANYTHING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: CLIMB - TO CRUISE

Findings

- 1. (C) IN-FLIGHT PLANNING/DECISION IMPROPER PILOT IN COMMAND
- 2. (C) PRESSURE PILOT IN COMMAND
- 3. (F) WEATHER CONDITION OBSCURATION
- 4. (C) VFR FLIGHT INTO IMC CONTINUED PILOT IN COMMAND
- 5. (C) WEATHER EVALUATION POOR PILOT IN COMMAND
- 6. (C) JUDGMENT POOR PILOT IN COMMAND
- 7. (C) IMPROPER USE OF EQUIPMENT/AIRCRAFT PILOT IN COMMAND
- 8. (F) WEATHER EVALUATION POOR COMPANY/OPERATOR MANAGEMENT

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: MANEUVERING

Findings

- 9. (F) TERRAIN CONDITION HIGH TERRAIN
- 10. (F) TERRAIN CONDITION SNOW COVERED
- 11. (F) WEATHER CONDITION CLOUDS
- 12. (F) WEATHER CONDITION WHITEOUT
- 13. (F) VISUAL/AURAL PERCEPTION PILOT IN COMMAND

Page 2 of 5 ANC85FA085

Factual Information

Pilot Information

Certificate:	Commercial	Age:	30, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	05/01/1985
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	4280 hours (Total, all aircraft), 420 hours (Total, this make and model), 4150 hours (Pilot In Command, all aircraft), 209 hours (Last 90 days, all aircraft), 79 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N73635
Model/Series:	C-207A C-207A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	20700610
Landing Gear Type:	Tricycle	Seats:	8
Date/Type of Last Inspection:	04/02/1985, 100 Hour	Certified Max Gross Wt.:	3800 lbs
Time Since Last Inspection:	85 Hours	Engines:	1 Reciprocating
Airframe Total Time:	5132 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	IO-520-F
Registered Owner:	DAVID OLSON	Rated Power:	300 hp
Operator:	DAVID OLSON	Operating Certificate(s) Held:	On-demand Air Taxi (135)

Page 3 of 5 ANC85FA085

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Day
Observation Facility, Elevation:	OME, 36 ft msl	Distance from Accident Site:	71 Nautical Miles
Observation Time:	1254 AKT	Direction from Accident Site:	256°
Lowest Cloud Condition:	Partial Obscuration / 0 ft agl	Visibility	15 Miles
Lowest Ceiling:	Overcast / 400 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	24 knots / 29 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	100°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	1°C / -1°C
Precipitation and Obscuration:			
Departure Point:	GOLOVIN, AK (GLV)	Type of Flight Plan Filed:	Company VFR
Destination:	ELIM, AK (ELI)	Type of Clearance:	None
Departure Time:	0000	Type of Airspace:	Class G

Airport Information

Airport:	UNKNOWN	Runway Surface Type:		
Airport Elevation:	0 ft	Runway Surface Condition:		
Runway Used:	0	IFR Approach:	None	
Runway Length/Width:		VFR Approach/Landing:	None	

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	2 Fatal, 2 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Fatal, 3 Serious	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	GEORGE	KOBELNYK	Report Date:	
Additional Participating Persons:	ROY C DAW	; ANCHORAGE, AK		
Publish Date:				
Investigation Docket:	investigation Record Mar	ons. Dockets released pri	serve as permanent archival informor to June 1, 2009 are publicly availaing@ntsb.gov, or at 800-877-6799. Dis.ntsb.gov/pubdms/.	able from the NTSB's

Page 4 of 5 ANC85FA085

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 ANC85FA085