

# National Transportation Safety Board Aviation Accident Final Report

Location: OSHTEMO TOWNSHP, MI Accident Number: CHI88FA010

**Date & Time:** 10/23/1987, 0332 EDT **Registration:** N554AC

Aircraft: Smith, Ted Aerostar AEROSTAR 600 Aircraft Damage: Destroyed

Defining Event: Injuries: 1 Fatal

Flight Conducted Under: Part 135: Air Taxi & Commuter - Non-scheduled

## **Analysis**

THE AIRCRAFT WAS AT CRUISE ALTITUDE (9,000 FEET) FOR APPROXIMATELY 20 MINUTES WHEN THE PILOT REPORTED THE LOSS OF RIGHT ENGINE POWER. CHICAGO ARTCC REPORTED THE CLOSEST AIRPORT WAS KALAMAZOO, 28 MILES WEST. THE AIRCRAFT BEGAN TO DESCEND AND AT 0330:53 CHICAGO ARTCC REPORTED N554AC WAS APPROXIMATELY 6 MILES FROM KALAMAZOO AIRPORT. THE PILOT REPORTED 'MY RIGHT ENGINE COWLING IS GONE...I DON'T KNOW IF I'M GOING TO MAKE IT.' WITNESSES OBSERVED THE AIRCRAFT AT 'TREE TOP LEVEL' AND IMPACT IN A HEAVILY WOODED AREA NEAR INTERSTATE 94, 5 MILES FROM THE AIRPORT. INVESTIGATION REVEALED IMPROPERWELD REPAIRS TO THE RIGHT ENGINE CASE AND SEPARATION OF THE NUMBER 2 CYLINDER FROM THE CASE DUE TO FATIGUE CRACKING IN THE THROUGH BOLTS AND STUDS. THE TOP SECTION OF THE ENGINE COWLING SEPARATED DUE TO THE FORCE OF THE CYLINDER SEPARATION.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: CRUISE - NORMAL

#### **Findings**

- 1. 1 ENGINE FAILURE, TOTAL
- 2. ENGINE ASSEMBLY, CRANKCASE CRACKED
- 3. (C) MAINTENANCE, MAJOR REPAIR IMPROPER OTHER MAINTENANCE PERSONNEL
- 4. (C) ENGINE ASSEMBLY, OTHER FATIGUE
- 5. (C) ENGINE ASSEMBLY, CYLINDER SEPARATION
- 6. (C) COOLING SYSTEM, COWLING SEPARATION

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

#### **Findings**

7. (F) LIGHT CONDITION - BRIGHT NIGHT

8. (F) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

-----

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: DESCENT - UNCONTROLLED

#### **Findings**

9. (F) OBJECT - TREE(S)

Page 2 of 5 CHI88FA010

# **Factual Information**

### **Pilot Information**

Certificate:	Airline Transport; Flight Instructor	Age:	47, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine; Helicopter; Instrument Airplane	Toxicology Performed:	Yes
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	09/01/1987
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	3290 hours (Total, all aircraft), 101 hours (Total, this make and model), 173 hours (Last 90 days, all aircraft), 26 hours (Last 30 days, all aircraft)		

# Aircraft and Owner/Operator Information

· ·			
Aircraft Make:	Smith, Ted Aerostar	Registration:	N554AC
Model/Series:	AEROSTAR 600 AEROSTAR 6	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	60002960
Landing Gear Type:	Retractable - Tricycle	Seats:	2
Date/Type of Last Inspection:	10/13/1987, Continuous Airworthiness	Certified Max Gross Wt.:	5500 lbs
Time Since Last Inspection:	33 Hours	Engines:	2 Reciprocating
Airframe Total Time:	14254 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540-K1J5
Registered Owner:	AIR CONTINENTAL INC.	Rated Power:	290 hp
Operator:	AIR CONTINENTAL INC.	Operating Certificate(s) Held:	Air Cargo
Operator Does Business As:		Operator Designator Code:	DRNA

Page 3 of 5 CHI88FA010

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Bright
Observation Facility, Elevation:	SBN, 790 ft msl	Distance from Accident Site:	45 Nautical Miles
Observation Time:	0357 EDT	Direction from Accident Site:	230°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	1°C / 1°C
Precipitation and Obscuration:			
Departure Point:	MILWAUKEE, WI (MKE)	Type of Flight Plan Filed:	IFR
Destination:	CLEVELAND, OH (CLV)	Type of Clearance:	IFR
Departure Time:	0257 EDT	Type of Airspace:	Class E

### **Airport Information**

Airport:	KALAMAZOO (AZO)	Runway Surface Type:	
Airport Elevation:	0 ft	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced Landing; Straight-in

# Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	On-Ground
Total Injuries:	1 Fatal	Latitude, Longitude:	

# Administrative Information

Investigator In Charge (IIC):	EDWARD J MCAVOY	Report Date:	12/27/1988
Additional Participating Persons:	<ul><li>P. HANSEN; GRAND RAPIDS, MI</li><li>D. NODORFT; GRAND RAPIDS, MI</li><li>J. STABLEY; WILLIAMSPORT, PA</li></ul>		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:publing@ntsb.gov">publing@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.ntsb.gov/pubdms/">http://dms.ntsb.gov/pubdms/</a> .		

Page 4 of 5 CHI88FA010

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 CHI88FA010