

National Transportation Safety Board Aviation Accident Final Report

Location: COLUMBIA, MO Accident Number: BFO90MA023

Date & Time: 01/30/1990, 2205 CST Registration: G0B0B

Aircraft: Hawker Siddeley HS.125-35 Aircraft Damage: Destroyed

Defining Event: 1 Fatal, 1 Serious, 1

Minor

Flight Conducted Under: Part 91F: Special Flt Ops.

Analysis

THE ACFT WAS EN ROUTE AT 31,000 FT, WHEN THE LOW PRESSURE FUEL FILTER WARNING LIGHT ILLUMINATED. THE PLT DIVERTED TOWARD COLUMBIA, MO, BUT BEFORE REACHING COLUMBIA, BOTH ENGINES LOST POWER. SUBSEQUENTLY, THE ACFT CRASHED ABOUT 2 MI EAST OF THE ARPT. AN INVESTIGATION REVEALED THE FUEL WAS CONTAMINATED WITH WATER. THE FUEL FILTER DEICING SYSTEM WAS OPERATIONAL, BUT A POST-ACDNT EXAM REVEALED THE DEICING TANK WAS EMPTY. THIS WAS THE 2ND FLT SINCE THE DEICE TANK HAD BEEN SERVICED. THE MANUFACTURER'S INFO INDICATED THE SUPPLY TANK SHOULD HAVE PROVIDED ABOUT 3 TO 4 HRS OF FILTER DEICING OPERATION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: INADEQUATE PREFLIGHT BY THE PILOT(S), WATER CONTAMINATION OF THE FUEL, LOW LEVEL OF DEICE FLUID (METHANOL) IN THE DEICE TANK, AND SUBSEQUENT ICE BLOCKAGE OF THE FUEL FILTERS. DARKNESS WAS A RELATED FACTOR.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE

Findings

1. 2 ENGINES

- 2. (C) AIRCRAFT PREFLIGHT INADEQUATE PILOT IN COMMAND
- 3. (C) FLUID, FUEL WATER
- 4. (C) FLUID, ANTI-ICE ADDITIVE LOW LEVEL
- 5. (C) FUEL SYSTEM, FILTER ICE
- 6. (C) FLUID, FUEL BLOCKED (TOTAL)

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING

Findings

7. (F) LIGHT CONDITION - DARK NIGHT

8. TERRAIN CONDITION - ROUGH/UNEVEN

Occurrence #4: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING

Findings

9. OBJECT - TREE(S)

Page 2 of 5 BFO90MA023

Factual Information

Pilot Information

Certificate:	Airline Transport; Flight Instructor	Age:	28, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1525 hours (Total, all aircraft), 400 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hawker Siddeley	Registration:	G0B0B
Model/Series:	HS.125-35 HS.125-35	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	25069
Landing Gear Type:	Retractable - Tricycle	Seats:	10
Date/Type of Last Inspection:	01/25/1990, AAIP	Certified Max Gross Wt.:	21700 lbs
Time Since Last Inspection:	0 Hours	Engines:	2 Turbo Jet
Airframe Total Time:	8720 Hours	Engine Manufacturer:	Rolls-Royce
ELT:		Engine Model/Series:	522
Registered Owner:	SLENDER YOU (UK) LTD	Rated Power:	3360 lbs
Operator:		Operating Certificate(s) Held:	None

Page 3 of 5 BFO90MA023

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Dark
Observation Facility, Elevation:	COU, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	2150 CST	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-1°C / -4°C
Precipitation and Obscuration:			
Departure Point:	CROSSVILLE, TN (CSV)	Type of Flight Plan Filed:	IFR
Destination:	OLATHE, KS (IXD)	Type of Clearance:	IFR
Departure Time:	2030 CST	Type of Airspace:	Class D

Airport Information

Airport:	COLUMBIA REGIONAL (COU)	Runway Surface Type:	
Airport Elevation:	889 ft	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 Fatal, 1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 1 Serious, 1 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ROBERT	DICKENS	Report Date:	09/11/1992
Additional Participating Persons:				
Publish Date:				
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at publing@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .			

Page 4 of 5 BFO90MA023

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 BFO90MA023