

National Transportation Safety Board Aviation Accident Final Report

Location: AVALON, CA Accident Number: LAX00LA038

Date & Time: 11/21/1999, 1015 PST Registration: N97CC

Aircraft: Smith, Ted Aerostar AEROSTAR 600 Aircraft Damage: Destroyed

Defining Event: Injuries: 1 Fatal

Flight Conducted Under: Part 91: General Aviation - Personal

Analysis

The pilot/owner was performing a post maintenance check flight about 20 miles off shore. He was receiving visual flight advisories from a terminal radar approach facility while in level flight about 4,900 feet msl. Subsequently, the airplane started slowing then descending in a right spiral, and radar contact was lost about 1,000 feet msl. The pilot's body was recovered from the ocean. According to the autopsy report, the pilot had experienced sudden cardiac death secondary to an acute myocardial infarction due to atherosclerotic coronary artery disease. Tramadol, a painkiller not approved by the FAA for flight, was detected in a drug screen and may have masked the chest pain.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's in-flight loss of control due to physical incapacitation from sudden cardiac death secondary to an acute myocardial infarction.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING

Findings

1. (C) AIRCRAFT CONTROL - NOT POSSIBLE - PILOT IN COMMAND 2. (C) INCAPACITATION(CARDIOVASCULAR) - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

3. TERRAIN CONDITION - WATER

Page 2 of 6 LAX00LA038

Factual Information

On November 21, 1999, about 1015 hours Pacific standard time, a Smith Aerostar 600, N97CC, descended into the Pacific Ocean near Avalon, California. The airline transport rated pilot, the sole occupant, received fatal injuries. Visual meteorological conditions prevailed for the personal flight. The aircraft, owned and operated by the pilot under the provisions of 14 CFR Part 91, was destroyed in the collision sequence and sank to the ocean bottom. No flight plan was filed for the local area flight, which originated at Fullerton, California, about 0930.

According to a family member, the pilot was accomplishing a post maintenance flight check.

Review of information and radar data provided by the Federal Aviation Administration (FAA) disclosed that the pilot was receiving visual flight advisories from Southern California Terminal Radar Approach Control. At 1015, radar contact was lost on the 200-degree radial of the Seal Beach VOR at 20 miles. Recorded radar data revealed that the mode C return was level at 4,900 feet mean sea level (msl) and exhibited a slowing ground speed. The secondary beacon returns then started a descending right spiral and radar contact was lost at 1,000 feet msl.

The pilot's body was recovered from the ocean and an autopsy was conducted by the Los Angeles County Coroner's office. According to the autopsy report, the pilot had experienced sudden cardiac death secondary to an acute myocardial infarction due to atherosclerotic coronary artery disease. The attesting pathologist opined that the event began from 30 minutes to several hours before the pilot's death. Tramadol, a painkiller not approved by the FAA for flight, was detected in blood and tissue samples submitted for toxicological tests. The pathologist stated that the drug may have masked the chest pain symptoms of the cardiac event.

The aircraft was not recovered. Review of the maintenance records disclosed that on November 5, 1999, the oil was changed on both engines. During engine run-up a "hot" or non-grounding magneto was found on the right engine. A loose "P" lead for grounding the magneto was discovered and reattached. At the same time, a broken exhaust flange was discovered on the No. 6 engine cylinder. Subsequently, the entire exhaust system and a gas temperature probe were replaced on the right engine. According to maintenance records, the last annual inspection occurred on July 16, 1999.

Page 3 of 6 LAX00LA038

Pilot Information

Certificate:	Airline Transport	Age:	44, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	03/26/1999
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1710 hours (Total, all aircraft), 851 days, all aircraft)	hours (Total, this make and model), 19	00 hours (Last 90

Aircraft and Owner/Operator Information

Aircraft Make:	Smith, Ted Aerostar	Registration:	N97CC
Model/Series:	AEROSTAR 600 AEROSTAR 6	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	600154068
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	07/16/1999, Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:	1 Hours	Engines:	2 Reciprocating
Airframe Total Time:	4199 Hours	Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	TIO-540
Registered Owner:	WALTER L. CECIL	Rated Power:	290 hp
Operator:	WALTER L. CECIL	Operating Certificate(s) Held:	None

Page 4 of 6 LAX00LA038

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	LGB, 57 ft msl	Distance from Accident Site:	20 Nautical Miles
Observation Time:	0956 PST	Direction from Accident Site:	20°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Light and Variable /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16°C / 12°C
Precipitation and Obscuration:			
Departure Point:	FULLERTON, CA (FUL)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	
Departure Time:	0930 PST	Type of Airspace:	Class E

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	GEORGE E PETTERSON	Report Date:	05/09/2001
Additional Participating Persons:	RAY HANNA; LONG BEACH, CA		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve a investigations. Dockets released prior to Ju Record Management Division at publicq@ntsthis.com date are available at http://dms.ntsb. .	ne 1, 2009 are public <u>b.gov</u> , or at 800-877	ly available from the NTSB's

Page 5 of 6 LAX00LA038

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 6 of 6 LAX00LA038