

Brief of Accident (Continued)

WPR11FA052
File No. 30850

11/17/2010

Portland, OR

Aircraft Reg No. N25PJ

Time (Local): 15:53 PST

encountering a drainage swale that collapsed the nose gear. As the airplane was traversing the soft, wet field, its wheels partially sank into the ground. While decelerating, soil impacted the landing gear wheels and struts where wiring to the antiskid brake system was located. The crew said that there were no indications on any cockpit annunciator light of a system failure or malfunction; however, after the airplane came to a stop they observed that the annunciator light associated with the antiskid system for the No. 2 wheel was illuminated (indicating a system failure). The other three annunciator lights (one for each wheel) were not illuminated.

During the approach, the first officer had completed the landing data card by using a company-developed quick reference card. The quick reference card's chart, which contained some data consistent with the landing charts in the Airplane Flight Manual (AFM), did not have correction factors for tailwind conditions, whereas the charts in the AFM do contain corrective factors for tailwind conditions. The landing data prepared by the first officer indicated that 3,240 feet was required to stop the airplane on a dry runway in zero wind conditions, with a wet correction factor increasing stopping distance to 4,538 feet. The Vref speed was listed as 127 knots for their landing weight of 11,000 pounds, and the first officer's verbal and written statements noted that they crossed the runway threshold at 125 knots. During the investigation, Bombardier Lear calculated the wet stopping distances with an 8-knot tailwind as 5,110 feet.

The touchdown zone for runway 30 is 1,000 feet from the approach end. The crew's estimate of their touchdown location on the runway is about 1,200 feet from the approach end, yielding a remaining runway of 5,400 feet. On-duty controllers in the tower watched the landing and said that the airplane touched down in front of the tower at a taxiway intersection that is 1,881 feet from the approach end, which would leave about 4,520 feet of runway to stop the airplane. The controllers observed water spraying off the airplane's main landing gear just after touchdown.

Postaccident testing indicated that the brake system, including the brake wear, was within limits, with no anomalies found. No evidence of tire failure was noted. The antiskid system was removed from the airplane for functional tests. The control box and the left and right control valves tested within specifications. The four wheel speed sensors met the electrical resistance specification. For units 1, 2 and 3, the output voltages exceeded the minimum specified voltages for each of the listed frequencies. Unit 4 was frozen and could not be rotated and thus could not be tested. Sensors 1 and 2 exceeded the specified 15% maximum to minimum voltage variation limit. Sensor 3 was within the limit and 4 could not be tested.

Based on all the evidence, it is likely that the airplane touched down on the water-contaminated runway beyond the touchdown zone, at a point with about 600 feet less remaining runway than the performance charts indicated that the airplane required for the wet conditions. Since a reverted rubber hydroplaning condition typically follows an encounter with dynamic hydroplaning, the reverted rubber signatures on the No. 2 tire indicate that the airplane encountered dynamic hydroplaning shortly after touchdown, and the left main gear wheel speed sensor anomalies allowed the left tires to progress to reverted rubber hydroplaning. This, along with postaccident testing, indicates that the anti-skid system was not performing optimally and, in concert with the hydroplaning conditions, significantly contributed to the lack of deceleration during the braking attempts.

Updated at Mar 26 2013 4:07PM

Brief of Accident (Continued)

WPR11FA052
File No. 30850

11/17/2010

Portland, OR

Aircraft Reg No. N25PJ

Time (Local): 15:53 PST

OCCURRENCES

Landing-flare/touchdown - Landing area overshoot
Landing-landing roll - Runway excursion
Landing-landing roll - Collision with terr/obj (non-CFIT)
Landing-landing roll - Landing gear collapse

FINDINGS

Aircraft-Aircraft oper/perf/capability-Performance/control parameters-Descent/approach/glide path-Not attained/maintained - C
Aircraft-Aircraft oper/perf/capability-Aircraft capability-Landing distance-Not attained/maintained - C
Personnel issues-Task performance-Use of equip/info-Aircraft control-Pilot - C
Organizational issues-Management-Resources-Adequacy of documents/info-Operator - F
Environmental issues-Physical environment-Runway/land/takeoff/taxi surfa-Wet-Contributed to outcome
Aircraft-Aircraft systems-Landing gear system-Anti-skid section-Not specified - C

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The failure of the flight crew to stop the airplane on the runway due to the flying pilot's failure to attain the proper touchdown point. Contributing to the accident was an anti-skid system that was not performing optimally, which allowed the airplane to encounter reverted rubber hydroplaning, and the company-developed quick reference landing distance chart that did not provide correction factors related to tailwind conditions.