National Transportation Safety Board Washington, DC 20594

Printed on: 11/1/2013 5:58:22 PM

Total Instrument Time: UnK/Nr

Brief of Accident

Adopted 11/22/2011

WPR11FA078

Instrument Ratings
Airplane

File No. 29057 12/20/2010 Perris, CA Aircraft Reg No. N316KW Time (Local): 10:00 PST Make/Model: Aero Commander / 680FL Fatal Serious Minor/None Engine Make/Model: Lycoming / IGSO-540-B1A Crew 0 1 0 Aircraft Damage: Substantial Pass 0 0 0 Number of Engines: 2 Operating Certificate(s): None Type of Flight Operation: Personal Reg. Flight Conducted Under: Part 91: General Aviation Last Depart. Point: Palm Springs, CA Condition of Light: Day Destination: Chino Airport, CA Weather Info Src: Weather Observation Facility Airport Proximity: Off Airport/Airstrip Basic Weather: Instrument Conditions Lowest Ceiling: 1200 Ft. AGL, Overcast Visibility: 10.00 SM Wind Dir/Speed: 140 / 011 Kts Temperature (°C): 11 Precip/Obscuration: Light - Drizzle; No Obscuration Pilot-in-Command Age: 65 Flight Time (Hours) Certificate(s)/Rating(s) Total All Aircraft: 33000 Airline Transport; Multi-engine Land; Single-engine Land; Single-engine Sea Last 90 Days: Unk/Nr Total Make/Model: Unk/Nr

*** Note: NTSB investigators either traveled in support of this investigation or conducted a significant amount of investigative work without any travel, and used data obtained from various sources to prepare this aircraft accident report. ***

The pilot departed the airport mid-morning to fly to his home airport, 63 miles to the northwest. Weather conditions at the departure airport were visual flight rules (VFR), the weather at the destination airport was not reported, and the weather conditions en-route were marginal VFR. The global positioning system (GPS) track for the flight indicated that the airplane departed from the airport and headed west along a highway corridor flying approximately 1,000 feet above ground level (agl) through a mountain pass. For the majority of the flight, the airplane maintained altitudes between 900 feet and 1,200 feet agl. Twenty-nine minutes after takeoff, the airplane's GPS track turned southwest away from an area of concentrated precipitation and directly towards an isolated mountain peak that rose approximately 1,000 feet above the surrounding terrain. The pilot contacted the local air traffic control facility, reported his position and requested traffic advisories through the local airspace to his destination airport. About 6 minutes later, the pilot stated that he was having difficulty maintaining VFR and asked for an instrument flight rules (IFR)clearance. At the same time, the GPS track showed that the airplane came within 50 feet of the mountainous terrain. No further transmissions from the pilot were received. The final GPS position was recorded 1 minute later, at 500 feet agl and approximately half a mile from the crash site. The terrain rapidly ascended in this area and intersected the airplane's flight path over the remaining 1/2 mile. An airport located about 4 miles from the accident site and in an area of flat terrain 1,000 feet below the isolated mountain top, recorded weather at the time of the accident as few clouds at 900 feet agl, overcast clouds at 1,500 feet agl, and a variable ceiling between 1,200 and 1,800 feet agl, in drizzle. Weather radar

Brief of Accident (Continued)

WPR11FA078

File No. 29057 12/20/2010 Perris, CA Aircraft Reg No. N316KW Time (Local): 10:00 PST

images at the time of the accident depicted precipitation at the elevation and location of the accident site, indicating probable mountain obscuration.

Updated at Nov 22 2011 2:18PM

Brief of Accident (Continued)

WPR11FA078 File No. 29057

12/20/2010

Perris, CA

Aircraft Reg No. N316KW

Time (Local): 10:00 PST

OCCURRENCES

Maneuvering - Controlled flight into terr/obj (CFIT)

FINDINGS

Environmental issues-Conditions/weather/phenomena-Ceiling/visibility/precip-(general)-Response/compensation - C Personnel issues-Action/decision-Info processing/decision-Decision making/judgment-Pilot - C

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident to be:
The pilot's decision to continue visual flight into instrument meteorological conditions, which resulted in an in-flight collision with mountainous terrain.