

## NTSB Identification: DIA68A0034

14 CFR Part 135 Nonscheduled operation of MILLER AVIATION  
Aircraft: BEECH E18S, registration: N281FM

| FILE  | DATE        | LOCATION     | AIRCRAFT DATA    | INJURIES                 |   |     | FLIGHT  | PILOT DATA     |  |
|---|-------------|--------------|------------------|--------------------------|---|-----|---------|----------------|--|
|   |             |              |                  | F                        | S | M/N | PURPOSE |                |  |
| 3-1057  | 68/3/2      | SALISBURY,NC | BEECH E18S       | CR-                      | 1 | 1   | 0       | COMMERCIAL     | COMMERCIAL, FL.INSTR.,<br>AGE 42, 5539 TOTAL HOURS,<br>5 IN TYPE, INSTRUMENT<br>RATED. |
|   | TIME - 0045 |              | N281FM           | PX-                      | 0 | 1   | 0       | AIR TAXI-CARGO |  |
|   |             |              | DAMAGE-DESTROYED | OT-                      | 0 | 0   | 0       |                |  |
| NAME OF AIRPORT - ROWAN COUNTY  |             |              |                  |                          |   |     |         |                |  |
| TYPE OF ACCIDENT  |             |              |                  | PHASE OF OPERATION       |   |     |         |                |  |
| FIRE OR EXPLOSION: IN FLIGHT  |             |              |                  | IN FLIGHT: NORMAL CRUISE |   |     |         |                |  |
| COLLIDED WITH: TREES  |             |              |                  | LANDING: FINAL APPROACH  |   |     |         |                |  |
| PROBABLE CAUSE(S)   |             |              |                  |                          |   |     |         |                |  |
| MISCELLANEOUS ACTS,CONDITIONS - FIRE IN CABIN,COCKPIT,BAGGAGE COMPARTMENT     |             |              |                  |                          |   |     |         |                |  |
| EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND                  |             |              |                  |                          |   |     |         |                |  |
| REMARKS- FIRE OCCURRED AT REAR OF INST PANEL.SOURCE OF IGNITION UNDETERMINED. |             |              |                  |                          |   |     |         |                |  |

Full narrative is not available