

NTSB Identification: IAD70AI042

14 CFR Part 135 Scheduled operation of SHENANDOAH AIR
 Aircraft: BEECH E18S, registration: N403FW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0175	70/2/3 TIME - 1455	WEYERS CAVE,VA	BEECH E18S N403FW DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	AIRLINE TRANSPORT, AGE 40, 6394 TOTAL HOURS, 191 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SHENANDOAH VALLEY DEPARTURE POINT INTENDED DESTINATION WASH.NATL APT,DC WEYERS CAVE,VA TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION LANDING: TRAFFIC PATTERN-CIRCLING COLLISION WITH GROUND/WATER: CONTROLLED LANDING: LEVEL OFF/TOUCHDOWN PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS MISCELLANEOUS ACTS,CONDITIONS - ANTI-ICING/DEICING EQUIPMENT-IMPROPER OPERATION OF/OR FAILED TO USE MISCELLANEOUS ACTS,CONDITIONS - ICE-CARBURETOR WEATHER - CONDITIONS CONDUCIVE TO CARB./INDUCTION SYSTEM ICING COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES WEATHER BRIEFING - OTHER WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND SKY CONDITION CEILING AT ACCIDENT SITE BROKEN 1000 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 1 MILE OR LESS SNOW OBSTRUCTIONS TO VISION AT ACCIDENT SITE TEMPERATURE-F FOG 30 WIND DIRECTION-DEGREES WIND VELOCITY-KNOTS 330 15 TYPE OF WEATHER CONDITIONS TYPE OF FLIGHT PLAN VFR NONE FIRE AFTER IMPACT REMARKS- STRUCK HILLSIDE,FENCE AND BARN. BOTH PROPS FOUND FEATH. WEA BRIEF BY PIEDMONT AT DEST.						

Full narrative is not available