

NTSB Identification: NYC71AN064

14 CFR Part 91 General Aviation
 Aircraft: CESSNA 207, registration: N91119

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2041	70/11/19 TIME - 1847	LEWIS,NY	CESSNA 207 N91119 DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	COMMERCIAL, FL.INSTR., AGE 31, 4050 TOTAL HOURS, 200 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
BURLINGTON,VT		BUFFALO,NY				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLISION WITH GROUND/WATER: CONTROLLED				IN FLIGHT: OTHER		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
MISCELLANEOUS ACTS,CONDITIONS - UNWARRANTED LOW FLYING						
FACTOR(S)						
WEATHER - FOG						
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE						
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT						
MISSING AIRCRAFT - LATER RECOVERED						
SKY CONDITION				CEILING AT ACCIDENT SITE		
OVERCAST/LOWER SCATTERED				8000		
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE		
5 OR OVER(UNLIMITED)				NONE		
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TYPE OF WEATHER CONDITIONS		
FOG				VFR		
TYPE OF FLIGHT PLAN						
VFR						
FIRE AFTER IMPACT						
REMARKS- RECOVERY DATE 11/21/70. ACFT SEEN AT TREE TOP LEVEL PRIOR TO IMPACT WITH MNTN UPSLOPE. FOG PATCHES						

Full narrative is not available