

NTSB Identification: LAX72DUJ07

14 CFR Part 91 General Aviation
 Aircraft: BOEING B-17G, registration: N9324Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2811	71/7/12 TIME - 1530	TUCSON, ARIZ	BOEING B-17G N9324Z DAMAGE-DESTROYED	CR- 0 0 2 PX- 0 0 0 OT- 0 0 0	COMMERCIAL FIRE CONTROL	COMMERCIAL, FL. INSTR., AGE 35, 3020 TOTAL HOURS, 450 IN TYPE, NOT INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
TUCSON, ARIZ		LOCAL				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: EN ROUTE TO RELOADING AREA		
COLLISION WITH GROUND/WATER: CONTROLLED				LANDING: OTHER		
PROBABLE CAUSE(S)						
POWERPLANT - FUEL SYSTEM: RAM AIR ASSEMBLY						
MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE						
POWERPLANT - PROPELLER AND ACCESSORIES: OTHER						
FACTOR(S)						
TERRAIN - ROUGH/UNEVEN						
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 4 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
REMARKS- BAFFLE IN AIR INTAKE SCOOP SEPRTD FM NR 4 RESTRNG AIRFLOW TO CARB.1,2,3 PROPS MVD TO HI PTCH.						

Full narrative is not available