

# NTSB Identification: MKC72AK053

14 CFR Part 135 Scheduled operation of DONALD G.LUTHI  
 Aircraft: BEECH D18S, registration: N375C

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-0581	72/3/2	NR.BISMARCK,N DAK	BEECH D18S	CR-	0	1	0	COMMERCIAL	COMMERCIAL, AGE 46, 5079
	TIME - 2218		N375C	PX-	0	0	0	COMMUTER AIR CARRIER	TOTAL HOURS, UNK/NR IN
			DAMAGE-DESTROYED	OT-	0	0	0	AIR TAXI-CARGO S-D	TYPE, INSTRUMENT RATED.
		DEPARTURE POINT	INTENDED DESTINATION						
		DICKINSON,N DAK	BISMARCK,N DAK						
		TYPE OF ACCIDENT						PHASE OF OPERATION	
		COLLIDED WITH: WIRES/POLES						LANDING: INITIAL APPROACH	
		PROBABLE CAUSE(S)							
		PILOT IN COMMAND - IMPROPER IFR OPERATION							
		FACTOR(S)							
		PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.							
		MISCELLANEOUS ACTS,CONDITIONS - INSTRUMENTS-MISREAD OR FAILED TO READ							
		MISCELLANEOUS ACTS,CONDITIONS - ALTIMETER SETTING-INCORRECT							
		TERRAIN - HIGH OBSTRUCTIONS							
		MISSING AIRCRAFT - LATER RECOVERED							
		REMARKS- HIT PWR LINES ON VOR APCH.ALTS SET 30.89 AND 30.13 IN ACFT.APC TRSMT 29.75.WASNT WEARING GLASSES.							

Full narrative is not available