NTSB Identification: FTW76FRG15

14 CFR Part 91 General Aviation Aircraft: CONVAIR PBY-6, registration: N15KL

FILE	DATE	LOCATION	AIRCRAFT DATA		IES S M		FLIGHT PURPOSE	PILOT DATA
3-4163	75/8/18 TIME - 131	HARLINGEN,TX LØ	CONVAIR PBY-6 N15KL DAMAGE-DESTROYED	 0	0	0	MISCELLANEOUS FERRY	AIRLINE TRANSPORT, AGE 58, 2200 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - HARLINGEN INDUST
DEPARTURE POINT INTENDED DESTINATION

LADITNICEN TY LOCAL

HARLINGEN, TX LOCAL

TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION TAKEOFF: INITIAL CLIMB STALL IN FLIGHT: OTHER

PROBABLE CAUSE(S)

POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS

PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.

PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED

MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT

REMARKS- TEST HOP DUE REPLACE R ENG CARB. R ENG QUIT, PROP WASNT FEATH, GR DOWN.

Full narrative is not available