

NTSB Identification: IAD78FA046

14 CFR Part 135 Nonscheduled operation of WYMAN PILOT SE
Aircraft: BEECH B18G, registration: N180P

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0443	78/3/2	ROCKINGHAM,NC	BEECH B18G	CR-	0	1	0	ATP,FLIGHT INSTR., AGE
	TIME - 2020		N180P	PX-	0	0	0	30, 6500 TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0	0	2825 IN TYPE, INSTRUMENT
								RATED.
		NAME OF AIRPORT - ROCKINGHAM-HAMLET						
		DEPARTURE POINT		INTENDED DESTINATION				
		ROCKINGHAM,NC		PONTIAC,MI				
		TYPE OF ACCIDENT			PHASE OF OPERATION			
		COLLIDED WITH: WIRES/POLES			TAKEOFF: INITIAL CLIMB			
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		PILOT IN COMMAND - FAILED TO ABORT TAKEOFF						
		FACTOR(S)						
		PILOT IN COMMAND - SELECTED UNSUITABLE TERRAIN						
		MISCELLANEOUS ACTS,CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE						
		AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: SNOW ON RUNWAY						
		FIRE AFTER IMPACT						
		REMARKS- LAUNCHED FM SNOW CVRD RWY WITH 1/2IN SNOW ON WINGS.						

Full narrative is not available