

# NTSB Identification: NYC78FFA29

14 CFR Part 135 Nonscheduled operation of BRENNAN AND HA  
Aircraft: BEECH E18S, registration: N58H

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4331	78/9/1 TIME - 2046	LATHAM,NY	BEECH E18S N58H DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 51, 4618 TOTAL HOURS, 214 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ALBANY COUNTY						
DEPARTURE POINT		INTENDED DESTINATION				
ALBANY,NY		WINDSOR LOCKS,CT				
TYPE OF ACCIDENT			PHASE OF OPERATION			
ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB			
COLLISION WITH GROUND/WATER: CONTROLLED			LANDING: OTHER			
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.						
FACTOR(S)						
MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
FIRE AFTER IMPACT						
REMARKS- FAILED ENGINE NOT FEATHERED.						

Full narrative is not available