Aviation Safety Investigation Report 197900005

Aerostar TS-601

1 February 1979

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 197900005 Occurrence Type: Accident

Location: Charleville QLD

Date: 1 February 1979 **Time:** 0125

Highest Injury Level: Serious

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	1	0	0
Total	0	1	0	1

Aircraft Details: Aerostar TS-601

Registration: VH-CPH

Serial Number:

Operation Type: Freight Charter
Damage Level: Destroyed
Departure Point: Charleville QLD

Departure Time: N/A

Destination: Mt Isa QLD

Approved for Release: 17th August 1984

Circumstances:

After lift-off at 85 knots, the pilot noted a positive rate of climb before retracting the landing gear and flaps. He then felt the aircraft sink and noted a high indicated rate of descent. Although full power was applied the descent continued until the aircraft struck the runway in a slightly nose-up attitude. The aircraft slid across the overrun area and through a fence before coming to rest. Fire broke out and engulfed the wreckage. At the time of the accident the aircraft weight was more than 200 kg above the maximum allowable and the centre of gravity was 142 mm forward of the forward limit. The pilot had been unable to retain control of the aircraft during the initial climb phase when the flaps were retracted at a relatively low airspeed.