NTSB Identification: SEA66A0026

14 CFR Part 91 General Aviation Aircraft: STINSON V-77, registration: N60361

| FILE | DATE | LOCATION | AIRCRAFT DATA | | | IES S M | | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|----------|--|-----|---|------------|---|--------------------------------|--|
| 2-0932 | 65/10/16 TIME - 174 | | STINSON V-77 N60361 DAMAGE-DESTROYED | PX- | 1 | 0 | 0 | MISCELLANEOUS DEMONSTRATION | COMMERCIAL, AGE 31, 5000 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED. |

NAME OF AIRPORT - STONE
TYPE OF ACCIDENT
COLLIDED WITH: DIRT BANK
PROBABLE CAUSE(S)
PILOT IN COMMAND - DELAYED IN INITIATING GO-AROUND
FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - SEAT BELT NOT FASTENED FIRE AFTER IMPACT

Full narrative is not available