

NTSB Identification: CHI65A0067

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT E18S, registration: N208UB

FILE	DATE	LOCATION	AIRCRAFT DATA		INJURIES	FLIGHT	PILOT DATA
			F	S/M/N			
2-0599	65/1/3	HENDERSON KY	BEECHCRAFT	E18S	CR- 1 0 0	NONCOMMERCIAL	COMMERCIAL, AGE 45, 4341
			TIME - 1445	N208UB	PX- 3 0 0	BUSINESS	TOTAL HOURS, 174 IN TYPE,
					DAMAGE-DESTROYED	OT- 0 0 0	NOT INSTRUMENT RATED.
TYPE OF ACCIDENT			PHASE OF OPERATION				
PROPELLER/ROTOR FAILURE: PROPELLER			IN FLIGHT: NORMAL CRUISE				
ENGINE TEARAWAY			IN FLIGHT: NORMAL CRUISE				
PROBABLE CAUSE(S)							
POWERPLANT - PROPELLER SYSTEM: BLADES							
MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE							
MISCELLANEOUS ACTS,CONDITIONS - SEPARATION IN FLIGHT							
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: IMPROPER MAINTENANCE (MAINTENANCE PERSONNEL)							
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE INSPECTION OF AIRCRAFT (MAINTENANCE PERSONNEL)							
FACTOR(S)							
MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER							
FIRE AFTER IMPACT							
REMARKS- NO.1 ENGINE TEARAWAY FOLLOWING IN-FLIGHT-SEPARATION OF NO.1 ENGINE PROPELLER BLADE.							

Full narrative is not available