

NTSB Identification: LAX70A0005

14 CFR Part 91 General Aviation
 Aircraft: PIPER PA-31, registration: N9150Y

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2807	69/7/18 TIME - 0524	BURBANK, CALIF	PIPER PA-31 N9150Y DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 1 0 OT- 0 0 0	COMMERCIAL CTR CARGO-D	COMMERCIAL, FL. INSTR., AGE 26, 1825 TOTAL HOURS, 162 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - HOLLYWOOD-BURBANK DEPARTURE POINT BURBANK, CALIF INTENDED DESTINATION FRESNO, CALIF TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION PHASE OF OPERATION TAKEOFF: RUN STALL: MUSH TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - FAILED TO ABORT TAKEOFF POWERPLANT - IGNITION SYSTEM: SPARK PLUG MISCELLANEOUS ACTS, CONDITIONS - CARBON DEPOSITS PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE REMARKS- OBS HEARD ENG BACKFIRING.PX BETWEEN P,CP WITH NO SEAT OR BELT.NEAR GROSS WT,CARGO NOT TIED DOWN.						

Full narrative is not available