

NTSB Identification: DEN72AD042

14 CFR Part 91 General Aviation

Aircraft: LOCKHEED 188, registration: N851U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
1-0010	72/3/19	HILL AFB,UT	LOCKHEED 188 N851U TIME - 0007 DAMAGE-SUBSTANTIAL	CR- 0 0 3 PX- 0 0 0 OT- 0 0 0			FERRY	AIRLINE TRANSPORT, AGE 47, 15000 TOTAL HOURS, 2500 IN TYPE, INSTRUMENT RATED.
			NAME OF AIRPORT - HILL AFB OPERATOR - UNIVERSAL AIRLINES, INC. DEPARTURE POINT TUCSON, ARIZ TYPE OF ACCIDENT PROPELLER/ROTOR FAILURE: PROPELLER FIRE OR EXPLOSION: IN FLIGHT PROBABLE CAUSE(S) POWERPLANT - PROPELLER SYSTEM: OTHER MISCELLANEOUS ACTS, CONDITIONS - PRESSURE TOO LOW PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT PERSONNEL - FLIGHT ENGINEER: IMPROPER USE OF EQUIPMENT MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES				INTENDED DESTINATION HILL AFB,UT PHASE OF OPERATION IN FLIGHT: DESCENDING LANDING: FINAL APPROACH	
			FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - FIRE IN ENGINE REMARKS- LOW OIL LVL LITE ILLUMNTD.PROP OVRSPED DRG FTHR,INSFCNT OIL,UNK REASON.ENG OIL SUPPLY NOT RESTORED					

Full narrative is not available