NTSB Identification: CHI73AC057

14 CFR Part 91 General Aviation Aircraft: HAWKER-SDLY DH125, registration: N521M

FILE	DATE LOCA	TION AIRC	AIRCRAFT DATA		INJURIES F S M/N				PILOT DATA	
3-3744	72/12/12 FINDLAY, TIME - 1938	N521M	SDLY DH125 DESTROYED	PX-	0	0	5		AIRLINE TRANSPORT, AGE 47, 10966 TOTAL HOURS, 2117 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - FINDLAY									
	DEPARTURE POINT		DESTINATION							
	FLUSHING, NY	FINDLAY	OHIO							
	TYPE OF ACCIDENT				PHASE OF OPERATION					
	COLLIDED WITH: TREES				LANDING: FINAL APPROACH					
	PROBABLE CAUSE(S)									
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING									
	PILOT IN COMMAND - IMPROPER IFR OPERATION FACTOR(S)									
	MISCELLANEOUS ACTS, CONDITIONS - CREW COORDINATION-POOR									
	WEATHER - LOW CEILING									
	WEATHER - FOG									
	WEATHER BRIEFING - BRIEFED BY WEATHER BUREAU PERSONNEL, IN PERSON									
	WEATHER FORECAST - I	FORECAST SUBSTANTIA	ALLY CORRECT							
	SKY CONDITION				CEILING AT ACCIDENT SITE					
	PARTIAL OBSCURATION				300					
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE					
	3/4 MILE OR LESS				DRIZZLE					
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F 36					
	FOG WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS					
	360				WIND VELOCITY-KNOTS					
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN					
	BELOW MINIMUMS				IFR					
	FIRE AFTER IMPACT									
	REMARKS- MISSED 2 STRAIGHT-IN VOR APCHS.ATTEMPTED VOR CIRCLING APCH IN BLO MINIMUM COND.DESCENDED BLO MDA.									

Full narrative is not available