NTSB Identification: IAD75AI001

14 CFR Part 91 General Aviation Aircraft: BEECH 65-90, registration: N113TC

FIRE AFTER IMPACT

REMARKS- R ENG OIL LINE TO COOLER FITTING DISCONNECTED.FULL R TRIM.

FILE	DATE LOCA	TION AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA	
3-1857	74/7/16 KNOXVILL TIME - 1048	E,TENN BEECH 65-90 N113TC DAMAGE-DESTROYED	PX- 0	0	0		AIRLINE TRANSPORT, AGE 32, 5397 TOTAL HOURS, 36 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - D							
	DEPARTURE POINT							
	ONEIDA, TENN	HALEYVILLE,ALA						
	TYPE OF ACCIDENT			PHAS	E O	F OPERATION		
	ENGINE FAILURE OR MALFUNCTION		IN FLIGHT: OTHER					
	STALL: SPIN			LANDING: GO-AROUND				
	PROBABLE CAUSE(S)							
	PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION							
	POWERPLANT - LUBRICATING SYSTEM: LINES,HOSES,FITTING							
	MISCELLANEOUS ACTS,CONDITIONS - DISCONNECTED							
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
	FACTOR(S)							
	MISCELLANEOUS ACTS,CONDITIONS - INCORRECT TRIM SETTING							
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE							
	EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING ON AIRPORT							

Full narrative is not available