NTSB Identification: MKC75AK037

14 CFR Part 135 Scheduled operation of AIR-MIDWEST Aircraft: CESSNA 402B, registration: N1415G

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N				PILOT DATA	
3-0216	75/1/31 TIME - 0911		N1415G	PX-	a 1	0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	TOTAL HOURS, 320 IN TYPE,	
	NAME OF AIRPORT - DODGE CITY MUNI								
				LAST ENROUTE STOP					
	WICHITA,KS			GARDEN CITY, KS					
	TYPE OF ACCIDENT			PHASE OF OPERATION					
	COLLISION WITH GROUND/W		ER: CONTROLLED LANDING: MISSED APPROACH						
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.								
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING								
	FACTOR(S)								
	MISCELLANEOUS ACTS,CONDITIONS - ICE-WINDSHIELD								
	MISCELLANEOUS ACTS,CONDITIONS - AIRFRAME ICE								
	WEATHER - ICING CONDITIONS-INCLUDES SLEET,FREEZING RAIN,ETC.								
	MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE								
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO								
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								
		ORCED LANDING OFF AIRPO							
	SKY CONDITION	ON			CEILING AT ACCIDENT SITE 400				
	OVERCAST VISIBILITY AT ACCIDENT SITE			100					
	2 MILES OR LESS				PRECIPITATION AT ACCIDENT SITE FREEZING DRIZZLE				
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F				
	FOG			21					
		THER CONDITIONS					FLIGHT PLAN		
	IFR OF WEA	CONDITIONS				FR	, EIGHT I EAR		
	REMARKS- VIS REF ESTB WINDSHIELD DEICER TURNED OFF.WINDSHIELD ICED OVR.UN CONT FLT DUE ICE ACCUMULATION.								

Full narrative is not available