

NTSB Identification: ANC76AA081

14 CFR Part 135 Nonscheduled operation of KENAI AIR SERV
 Aircraft: BEECH 65-90, registration: N2400X

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3138	76/4/17	AKUTAN ISLAND,AK	BEECH 65-90	CR-	0	0	2	COMMERCIAL	COMMERCIAL, AGE 33, 6350
	TIME - 1020		N2400X	PX-	0	0	3	AIR TAXI-PASSG	TOTAL HOURS, 61 IN TYPE,
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		INSTRUMENT RATED.
	DEPARTURE POINT		INTENDED DESTINATION						
	KENAI,AK		DUTCH HARBOR,AK						
	TYPE OF ACCIDENT								
	DITCHING								
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING								
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL								
	FACTOR(S)								
	MISCELLANEOUS ACTS,CONDITIONS - MISCALCULATED FUEL CONSUMPTION								
	AIRPORTS/AIRWAYS/FACILITIES - AIRWAYS FACILITIES: H. FACILITY								
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER								
	EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING OFF AIRPORT								
	LOW ON FUEL								
	REMARKS- PILOT DITCHED AIRCRAFT DUE TO LOW FUEL STATE. DRIFTWOOD BAY BEACON INOP DUE ANTENNA DMG.								

Full narrative is not available