

# NTSB Identification: LAX75AL038

14 CFR Part 91 General Aviation  
 Aircraft: CONVAIR PBY-5A, registration: N5588W

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0339	75/2/6 TIME - 2130	NR.WIKIEUP,AZ	CONVAIR PBY-5A N5588W DAMAGE-DESTROYED	CR- 3 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL BUSINESS	PRIVATE, AGE 38, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT LAS VEGAS,NV	INTENDED DESTINATION EL PASO, TX			PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE LANDING: ROLL	
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLIDED WITH: DIRT BANK					
	PROBABLE CAUSE(S) POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.					
	FACTOR(S) TERRAIN - ROUGH/UNEVEN MISCELLANEOUS ACTS,CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT					
	REMARKS- PLT DECLARED BOTH ENGS LOST PWR. ATTMPTD LDG BESIDE HIWAY IN DESERT.NO RECORDS FOR OTR CREW PERS.					

Full narrative is not available