NTSB Identification: OAK77DJA10

14 CFR Part 91 General Aviation Aircraft: CESSNA 340, registration: N7839Q

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA
3-0590	TIME - 00	POINT	N7839Q DAMAGE-DESTROYED INTENDED DESTINATION	PX- (9 6)	0		COMMERCIAL, AGE 22, 3500 TOTAL HOURS, 31 IN TYPE, INSTRUMENT RATED.
	PAGO PAGO,AMER SAMOA HONOLULU,HI TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION IN FLIGHT: NORMAL CRUISE DITCHING LANDING: LEVEL OFF/TOUCHDOWN PROBABLE CAUSE(S) POWERPLANT - FUEL SYSTEM: TANKS MISCELLANEOUS ACTS,CONDITIONS - LEAK/LEAKAGE MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER REMARKS- FUEL LEAK LEFT TIP TANK,UNK ORIGIN.DITCHED 28NM SW OF HAWAII.								

Full narrative is not available