## NTSB Identification: ANC78DA038

14 CFR Part 135 Nonscheduled operation of GIFFORD AVIATI Aircraft: GRUMMAN G-21A, registration: N1042

FILE	DATE LOCATION	AIRCRAFT DATA			RIES S N		FLIGHT PURPOSE	PILOT DATA
3-3529	78/5/12 NR.PORT MOLLER,AK TIME - 1340	GRUMMAN G-21A N1042 DAMAGE-DESTROYED	PX-	0	0	2	COMMERCIAL AIR TAXI-PASSG	AIRLINE TRANSPORT, AGE 30, 2855 TOTAL HOURS, 54 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT PORT MOLLER,AK TYPE OF ACCIDENT DRAGGED WINGTIP,POD,OR	INTENDED DESTINATION COLD BAY,AK			PHAS			
	PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF BRAKES PILOT IN COMMAND - FAILED TO ABORT TAKEOFF FACTOR(S) PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRC REMARKS- LAGOON-OPEN WATER.DURING TKOF RUN L WING F				FL:	[GH		PE.

Full narrative is not available