

NTSB Identification: FTW78FA068

14 CFR Part 135 Scheduled operation of TEJAS AIRLINES
Aircraft: SWEARINGEN SA226, registration: N300TL

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES	FLIGHT	PILOT DATA
				F S M/N	PURPOSE	
3-4247	78/8/13	AUSTIN,TX	SWEARINGEN SA226 N300TL DAMAGE-DESTROYED	CR- 0 1 1 PX- 0 1 15 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	ATP,FLIGHT INSTR., AGE 29, 4985 TOTAL HOURS, 815 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ROBERT MUELLER						
DEPARTURE POINT		INTENDED DESTINATION				
SAN ANTONIO,TX		AUSTIN,TX				
TYPE OF ACCIDENT			PHASE OF OPERATION			
ENGINE FAILURE OR MALFUNCTION			LANDING: FINAL APPROACH			
GEAR RETRACTED			LANDING: ROLL			
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION						
PILOT IN COMMAND - FAILED TO ASSURE THE GEAR WAS DOWN AND LOCKED						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIPT.						
REMARKS- ACFT REFUELED IN R WING W 125GAL BFR 18MIN FLT.CROSSFLOW VALVE FOUND OFF.						

Full narrative is not available