

NTSB Identification: CHI78FA010

14 CFR Part 91 General Aviation
 Aircraft: LEARJET 25, registration: N100MK

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4451	78/10/20 TIME - 1033	VICKERY,OH	LEARJET 25 N100MK DAMAGE-DESTROYED	CR- 3 0 0 PX- 0 0 0 OT- 0 0 0	INSTRUCTIONAL CHECK	ATP, FLIGHT INSTR., AGE 29, 4800 TOTAL HOURS, 150 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT CLEVELAND,OH		INTENDED DESTINATION CLEVELAND,OH		PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE		
TYPE OF ACCIDENT AIRFRAME FAILURE: IN FLIGHT						
PROBABLE CAUSE(S) PERSONNEL - PRODUCTION-DESIGN-PERSONNEL: POOR/INADEQUATE DESIGN SYSTEMS - AUTO PILOT: SERVO MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE FIRE AFTER IMPACT						
REMARKS- ABRUPT NOSE DOWN PITCH.						

Full narrative is not available