

NTSB Identification: FTW79FPG15

14 CFR Part 91 General Aviation
Aircraft: MITSUBISHI MU-2B, registration: N5NW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0122	79/1/23	SEARCY, AR	MITSUBISHI MU-2B TIME - 0855	CR- N5NW DAMAGE-SUBSTANTIAL	0 0 0	0 2 0	1 CORP/EXEC 0	AIRLINE TRANSPORT, AGE 33, 3300 TOTAL HOURS, 1031 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SEARCY MUNICIPAL								
DEPARTURE POINT INTENDED DESTINATION								
OKLAHOMA CITY, OK SEARCY, AR								
TYPE OF ACCIDENT								
STALL: MUSH								
PROBABLE CAUSE(S)								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
FACTOR(S)								
PILOT IN COMMAND - FAILED TO INITIATE GO-AROUND								
MISCELLANEOUS ACTS, CONDITIONS - NOT ALIGNED WITH RUNWAY/INTENDED LANDING AREA								

Full narrative is not available