

NTSB Identification: MIA80FA029

14 CFR Part 135 Scheduled operation of EASTERN CARIB
 Aircraft: PIPER PA-31, registration: N25VM

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0177	80/1/18 TIME - 0743	ST.CROIX,VI	PIPER PA-31 N25VM DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 2 7 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	ATP, FLIGHT INSTR., AGE 25, 2864 TOTAL HOURS, 31 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - ALEX HAMILTON DEPARTURE POINT ST.CROIX,VI INTENDED DESTINATION ST THOMAS,VI TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLIDED WITH: TREES PROBABLE CAUSE(S) POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT REMARKS- GR CYCLED AFTR INITIAL PWR LOSS. FEATHERED ENG AFTR GETTING SURGE OF PWR BACK. TREES ON SHORELINE.						
Full narrative is not available						