

National Transportation Safety Board Aviation Accident Final Report

Location:	ILIAMNA, AK	Accident Number:	ANC83LA151
Date & Time:	08/20/1983, 1630 AKD	Registration:	N3129S
Aircraft:	de Havilland DHC-2	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	2 Serious, 3 Minor
Flight Conducted Under:	Part 135: Air Taxi & Commuter - Non-scheduled		

Analysis

THE ACFT GOT INTO A DOWNDRAFT AND COLLIDED WITH HILLY TERRAIN. THE PILOT STATED THAT HE WAS SPOTTING CARIBOU AND SETTLED INTO THE SIDE OF A HILL. ACCORDING TO THE PASSENGERS THE ACFT WAS ABOUT 300 FT AGL PRIOR TO THE DESCENT TO GROUND CONTACT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: MANEUVERING

Findings 1. (F) WEATHER CONDITION - DOWNDRAFT 2. (C) ALTITUDE - INADEQUATE - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING

Findings 3. (F) TERRAIN CONDITION - MOUNTAINOUS/HILLY

Factual Information

Pilot Information

Certificate:	Airline Transport; Commercial	Age:	33, Male
Airplane Rating(s):	Multi-engine Land; Multi-engine Sea; Single-engine Land; Single- engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	01/07/1983
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	9558 hours (Total, all aircraft), 1116 hours (Total, this make and model), 8848 hours (Pilot In Command, all aircraft), 71 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft), 12 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	de Havilland	Registration:	N3129S
Model/Series:	DHC-2 DHC-2	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	269
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	06/17/1983, 100 Hour	Certified Max Gross Wt.:	4500 lbs
Time Since Last Inspection:	90 Hours	Engines:	1 Reciprocating
Airframe Total Time:	7000 Hours	Engine Manufacturer:	P&W
ELT:	Installed, activated	Engine Model/Series:	R-985
Registered Owner:	ALASKA NORTH FLYING SERVICE	Rated Power:	450 hp
Operator:	ALASKA NORTH FLYING SERVICE	Operating Certificate(s) Held:	On-demand Air Taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0 °
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	80 Miles
Lowest Ceiling:	Broken / 4000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	13 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	13°C / 7°C
Precipitation and Obscuration:			
Departure Point:	ANCHORAGE, AK (ANC)	Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	1330 ADT	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Serious, 3 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious, 3 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JAMES	MICHELANGELO	Report Date:
Additional Participating Persons:			
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <u>pubing@ntsb.gov</u> , or at 800-877-6799. Dockets released after this date are available at <u>http://dms.ntsb.gov/pubdms/</u> .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <u>here</u>.