NTSB Identification: ANC71AA057

14 CFR Part 91 General Aviation Aircraft: STINSON V-77, registration: N5709N

_E	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA		
186	71/5/13 TIME - 1		STINSON V-77 N5709N DAMAGE-DESTROYED	PX-	0	0	0		PRIVATE, AGE 45, 1200 TOTAL HOURS, 440 IN TYPE NOT INSTRUMENT RATED.		
	NAME OF AIRPORT - TOBIN CREEK										
	DEPARTUR	E POINT	INTENDED DESTINATION								
	FAIRBA	NKS,ALAS	BETTLES,ALAS								
	TYPE OF ACCIDENT				PHASE OF OPERATION						
	STALL					I	N F	LIGHT: OTHER			
	PROBABLE CAUSE(S)										
	PILOT IN COMMAND - EXERCISED POOR JUDGMENT										
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED										
	FACTOR(S)										
	AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER										
	WEATHER - UNFAVORABLE WIND CONDITIONS										
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT										
			SUBSTANTIALLY CORRECT		_	СТІ	TNC	AT ACCIDENT SITE			
	SKY CONDITION CLEAR				UNLIMITED						
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE						
	5 OR OVER(UNLIMITED)				NONE						
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F						
	NONE					40					
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN						
	VFR						NONE				
	REMARKS- STEEP L BANK FROM LOW PASS AT STRIP LOCATED BETWEEN CLOSE-IN MNTNS. OBS REPTD WIND STRONG, GUSTY.										

Full narrative is not available