

# National Transportation Safety Board Aviation Accident Final Report

Location: PHILADELPHIA, PA Accident Number: NYC89LA143

Date & Time: 06/01/1989, 1139 Registration: N5AN

Aircraft: BEECH 60 Aircraft Damage: Destroyed

Defining Event: Injuries: 3 None

Flight Conducted Under: Part 91: General Aviation - Personal

### **Analysis**

THE AIRCRAFT MADE A HARD LANDING, RAN OFF THE RIGHT SIDE OF THE RUNWAY AND COLLIDED WITH THE TERRAIN. SUBSEQUENTLY, THE PLANE ERUPTED IN FLAMES AND WAS DESTROYED, BUT THE PILOT AND PASSENGERS WERE NOT INJURED.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER FLARE BY THE PILOT DURING THE LANDING, AND HIS FAILURE TO MAINTAIN DIRECTIONAL CONTROL OF THE AIRCRAFT.

#### **Findings**

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

**Findings** 

1. (C) FLARE - IMPROPER - PILOT IN COMMAND

-----

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

**Findings** 

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. GROUND LOOP/SWERVE - UNCONTROLLED

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

Page 2 of 5 NYC89LA143

## **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	35, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	02/03/1988
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	650 hours (Total, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N5AN
Model/Series:	60 60	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	P-542
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	6725 lbs
Time Since Last Inspection:	0 Hours	Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	TIO-541
Registered Owner:	AWAA AVIATION, INC.	Rated Power:	380 hp
Operator:	AWAA AVIATION, INC.	Operating Certificate(s) Held:	None

Page 3 of 5 NYC89LA143

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	0 Miles
Lowest Ceiling:	Unknown / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	Unknown
Destination:		Type of Clearance:	
Departure Time:	0000	Type of Airspace:	

### **Airport Information**

Airport:	MOORHEAD (PA08)	Runway Surface Type:	Gravel
Airport Elevation:	805 ft	Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:	2085 ft / 180 ft	VFR Approach/Landing:	Traffic Pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:	2 None	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	On-Ground
Total Injuries:	3 None	Latitude, Longitude:	

## Administrative Information

Investigator In Charge (IIC):	REUBEN L DENSLEY	Report Date:	06/16/1992
Additional Participating Persons:			
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:publing@ntsb.gov">publing@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.ntsb.gov/pubdms/">http://dms.ntsb.gov/pubdms/</a> .		

Page 4 of 5 NYC89LA143

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 NYC89LA143