

# NTSB Identification: ANC65A0039

14 CFR Part 91 General Aviation  
Aircraft: FAIRCHILD C82, registration: N208M

FILE	DATE	LOCATION	AIRCRAFT DATA F S M/N	PURPOSE	INJURIES	FLIGHT	PILOT DATA
2-0260	65/1/16	NR.BEAVER ALAS	FAIRCHILD C82	CR- 0 0 3	MISCELLANEOUS	AIRLINE TRANSPORT, AGE	
	TIME - 1705	N208M	PX- 0 0 0	FERRY	48,16687	TOTAL HOURS, 26	
		DAMAGE-SUBSTANTIAL	OT- 0 0 0			IN TYPE, INSTRUMENT	
						RATED.	
						TYPE OF ACCIDENT	
						ENGINE FAILURE OR MALFUNCTION	
						COLLIDED WITH: TREES	
						PROBABLE CAUSE(S)	
						MISCELLANEOUS ACTS,CONDITIONS - ANTI-ICING/DEICING EQUIPMENT-IMPROPER OPERATION OF/OR FAILED TO USE	
						MISCELLANEOUS ACTS,CONDITIONS - ICE-CARBURETOR	
						FACTOR(S)	
						MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES	
						WEATHER - CONDITIONS CONDUCIVE TO CARB./INDUCTION SYSTEM ICING	
						PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE	
						COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE	
						WEATHER BRIEFING - OTHER	
						WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT	
						EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND	
						SKY CONDITION	
						OVERCAST	
						VISIBILITY AT ACCIDENT SITE	
						5 OR OVER(UNLIMITED)	
						OBSTRUCTIONS TO VISION AT ACCIDENT SITE	
						BLOWING SNOW	
						WIND VELOCITY-KNOTS	
						8	
						TYPE OF FLIGHT PLAN	
						VFR	
						REMARKS- PLT RECIEVED A REPORT OF ENROUTE SKY CONDITIONS FROM AIRLINE PILOT BUT DID NOT RECVE A WX BRIEFING	

Full narrative is not available