## NTSB Identification: Unknown

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT G18S, registration: N9423Y

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT D F S M/N PURPOSE

2-0912 64/7/16 NR.TOADLENA N MEX BEECHCRAFT G18S CR- 1 0 0 NONCOMMERCIAL AIRLINE TRANSPORT, AGE

TIME - 1225 N9423Y PX- 3 0 0 CORP/EXEC 42, 11280 TOTAL HOURS,

DAMAGE-DESTROYED OT- 0 0 0 UNK/NR IN TYPE,

INSTRUMENT RATED.

TYPE OF ACCIDENT PHASE OF OPERATION

AIRFRAME FAILURE: IN FLIGHT IN FLIGHT: NORMAL CRUISE

PROBABLE CAUSE(S)

AIRFRAME - WINGS: SPARS

MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE

FACTOR(S)

WEATHER - TURBULENCE, ASSOCIATED W/CLOUDS AND/OR THUNDERSTORMS

WEATHER - DOWNDRAFT, UPDRAFTS

WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON

WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT

SKY CONDITION CEILING AT ACCIDENT SITE

BROKEN 14000

VISIBILITY AT ACCIDENT SITE OBSTRUCTIONS TO VISION AT ACCIDENT SITE

3 MILES OR LESS BLOWING DUST

TEMPERATURE-F WIND DIRECTION-DEGREES

51 220

WIND VELOCITY-KNOTS TYPE OF WEATHER CONDITIONS

50 VFR

TYPE OF FLIGHT PLAN

VFR

FIRE AFTER IMPACT

REMARKS- LAST PERIODIC INSPECTION OF N9423Y WAS PERFORMED 3/1/64 AT 2130 TOTAL AIRCRAFT HOURS.

Full narrative is not available