## NTSB Identification: MIA65A0082

14 CFR Part 129 Nonscheduled operation of OTHER-FOREIGN FLAG CARRIER Aircraft: CURTISS C-46A, registration: YS-012C

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

A-0002 65/2/13 MIAMI,FLA CURTISS C-46A CR- 2 0 0 NS/CTR REVENUE CARGO INTLAIRLINE TRANSPORT, AGE

YS-012C PX- 0 0 0 45, 14606 TOTAL HOURS, DAMAGE-DESTROYED OT- 0 0 0 2353 IN TYPE, INSTR TIME - 0420 2353 IN TYPE, INSTRUMENT

RATED.

NAME OF AIRPORT - MIAMI INTL

OPERATOR - OTHER-FOREIGN FLAG CARRIER

TYPE OF ACCIDENT

ENGINE FAILURE OR MALFUNCTION COLLISION WITH COOK COLLISION WITH GROUND/WATER: CONTROLLED

ROBABLE CAUSE(S)

TAKEOFF: INITIAL CLIMB
TAKEOFF: INITIAL CLIMB

TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)

POWERPLANT - ENGINE STRUCTURE: CRANKSHAFT

MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE

PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION

MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE

EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND

FIRE AFTER IMPACT

 $REMARKS-AEROLINAS\;EL\;SALVADORE\;S.A.CARGO\;FLT.\;FAILURE\;OFL.PROP.TO\;FEATHER.PROBABLY.DUE\;OIL\;CONTAMINATION\;PROPERTY OF STREET STREET, FROM STREET STREET, FROM STREET STREET, FROM STREET,$ 

Full narrative is not available