NTSB Identification: MKC66A0018

14 CFR Part 91 General Aviation Aircraft: CONVAIR CV-880, registration: N820TW

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA F S M/N PURPOSE

1-0021 65/9/13 KANSAS CITY MO CONVAIR CV-880 CR- 0 0 4 TRAINING TIME - 1240 N820TW PX- 0 0 0 50, 17410 TOTA AIRLINE TRANSPORT, AGE

1300 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - MID-CONTINENT INT

OPERATOR - TRANS WORLD AIRLINES, INC.

TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION

TAKEOFF: RUN STALL: MUSH TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)

DUAL STUDENT - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT MISCELLANEOUS ACTS, CONDITIONS - SIMULATED CONDITIONS

FIRE AFTER IMPACT

Full narrative is not available