NTSB Identification: CHI68A0054

14 CFR Part 121 Scheduled operation of UNITED AIR LINES INC Aircraft: VICKERS 745D, registration: N7429

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | | | | FLIGHT PURPOSE | PILOT DATA |
|--------|------------|--------------|-----------------------------|---------------------|---|---|----|---------------------|--|
| 1-0070 | TIME - 152 | CANTON, OHIO | N7429 DAMAGE-SUBSTANTIAL | PX- | 0 | 1 | 14 | SCHED DOM PASSG SRV | AIRLINE TRANSPORT, AGE 33, 11000 TOTAL HOURS, 8000 IN TYPE, INSTRUMENT RATED. |

NAME OF AIRPORT - AKRON-CANTON OPERATOR - UNITED AIR LINES,INC. TYPE OF ACCIDENT OVERSHOOT

PHASE OF OPERATION LANDING: ROLL LANDING: ROLL UVEKSHOUI
GEAR COLLAPSED
PROBABLE CAUSE(S)
PILOT IN COMMAND - MISJUDGED DISTANCE AND SPEED
PILOT IN COMMAND - FAILED TO INITIATE GO-AROUND
FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE

Full narrative is not available