

# NTSB Identification: MIA69F0473

14 CFR Part 91 General Aviation  
Aircraft: BEECH TC 45G, registration: N199H

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4841	68/2/17 TIME - 0700	CAYCE, SC	BEECH TC 45G N199H DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 3 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, AGE 41, 5600 TOTAL HOURS, 570 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - COLUMBIA			PHASE OF OPERATION	
		TYPE OF ACCIDENT			TAKEOFF: INITIAL CLIMB	
		STALL: MUSH				
		PROBABLE CAUSE(S)				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		PILOT IN COMMAND - EXERCISED POOR JUDGMENT				
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED				
		MISCELLANEOUS ACTS, CONDITIONS - WINDSHIELD, DIRTY, FOGGY, ETC. - RESTRICTED VISION				
		FIRE AFTER IMPACT				
		REMARKS- ACFT COVERED WITH FROST, ONLY THE WINDSHIELD CLEANED. CABIN HEAT INSUF TO PREVENT WINDSHIELD FOGGING				

Full narrative is not available