

NTSB Identification: CHI69A0033

14 CFR Part 91 General Aviation
Aircraft: DEHAVILLAND 104, registration: N6533D

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3599	68/9/21 TIME - 1504	RICHMOND, OHIO	DEHAVILLAND 104 N6533D DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	INSTRUCTIONAL DUAL	ATP, FLIGHT INSTR., AGE 29, 5060 TOTAL HOURS, 2240 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - CUYAHOGA COUNTY

TYPE OF ACCIDENT

ENGINE FAILURE OR MALFUNCTION

STALL

PROBABLE CAUSE(S)

MISCELLANEOUS ACTS, CONDITIONS - SIMULATED CONDITIONS

PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT

DUAL STUDENT - FAILED TO OBTAIN/MAINTAIN FLYING SPEED

MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES

FIRE AFTER IMPACT

REMARKS- INSTR PLT CUT RT ENG FUEL AFTER LIFTOFF. PLT RETARDED WRONG THROTTLE, DID NOT RAISE FLAPS. LOST CNTRL

PHASE OF OPERATION

TAKEOFF: INITIAL CLIMB

TAKEOFF: INITIAL CLIMB

Full narrative is not available