

NTSB Identification: SEA71DVQ03

14 CFR Part 91 General Aviation  
Aircraft: CONVAIR PB4Y-2, registration: N3191G

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3094	70/7/27	DIAMOND LAKE,OREG	CONVAIR PB4Y-2	CR-	0	0	2	COMMERCIAL
	TIME - 1415		N3191G	PX-	0	0	0	ASSOC FIRE CTL ACTIVITY
			DAMAGE-SUBSTANTIAL	OT-	0	0	0	COMMERCIAL, FL.INSTR.,
								AGE 53, 12707 TOTAL
								HOURS, 14 IN TYPE,
								INSTRUMENT RATED.
		DEPARTURE POINT	INTENDED DESTINATION					
		MEDFORD,OREG	MEDFORD,OREG					
		TYPE OF ACCIDENT					PHASE OF OPERATION	
		ENGINE FAILURE OR MALFUNCTION					IN FLIGHT: OTHER	
		DITCHING					LANDING: LEVEL OFF/TOUCHDOWN	
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
		MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
		FACTOR(S)						
		MISCELLANEOUS ACTS,CONDITIONS - JETTISONED LOAD						
		MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-3 ENGINES						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
		REMARKS- WATER 8 FT DEEP. NO FUEL GAGES ON ACFT.						

Full narrative is not available