

# NTSB Identification: DEN71FXA05

14 CFR Part 91 General Aviation  
 Aircraft: BOEING TB-17F, registration: N1340N

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2288	70/8/18 TIME - 1637	DUBOIS,WYO	BOEING TB-17F N1340N DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL FIRE CONTROL	COMMERCIAL, FL.INSTR., AGE 52, 8000 TOTAL HOURS, 105 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT CODY,WYO		INTENDED DESTINATION LOCAL		PHASE OF OPERATION IN FLIGHT: SWATH RUN IN FLIGHT: PULLUP FROM SWATH RUN		
TYPE OF ACCIDENT STALL: MUSH COLLIDED WITH: TREES		PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED				
FACTOR(S) WEATHER - DOWNDRAFT,UPDRAFTS WEATHER - HIGH DENSITY ALTITUDE		CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED				
WEATHER BRIEFING - OTHER WEATHER FORECAST - UNKNOWN/NOT REPORTED		PRECIPITATION AT ACCIDENT SITE NONE				
SKY CONDITION CLEAR		TEMPERATURE-F 89				
VISIBILITY AT ACCIDENT SITE UNKNOWN/NOT REPORTED		TYPE OF WEATHER CONDITIONS VFR				
OBSTRUCTIONS TO VISION AT ACCIDENT SITE SMOKE						
WIND DIRECTION-DEGREES 225						
TYPE OF FLIGHT PLAN NONE						
FIRE AFTER IMPACT						
REMARKS- FIRE DROP DOWN SLOPE SIDE OF MTN,DOWN WIND RUN.DENSITY ALT APRX 13000FT.WX BRFG,USFS.WIND 25-35MPH						

Full narrative is not available