

NTSB Identification: NYC71AN082

14 CFR Part 91 General Aviation
Aircraft: CESSNA 411, registration: N7386U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0156	71/1/19 TIME - 1221	LITTLE FERRY,NJ	CESSNA 411 N7386U DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	MISCELLANEOUS FERRY	COMMERCIAL, FL.INSTR., AGE 47, 6450 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - TETERBORO						
DEPARTURE POINT		INTENDED DESTINATION				
TETERBORO,NJ		ELMIRA,NY				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB		
COLLISION WITH GROUND/WATER: UNCONTROLLED				IN FLIGHT: UNCONTROLLED DESCENT		
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
FIRE AFTER IMPACT						
REMARKS- NO ENG MALFUNCTION FOUND.POSSIBLY INSUFFICIENT WARM UP TIME.PLT DIDNT MAINTAIN SINGLE ENG SPEED.						

Full narrative is not available