## NTSB Identification: SEA71AS033

14 CFR Part 91 General Aviation Aircraft: AERO COMDR 500, registration: N8473C

```
FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA
F S M/N PURPOSE
3-0134 71/1/9 CARSON,WASH AERO COMDR 500 CR- 1 0 0 NONCOMMERCIAL COMMERCIAL, AGE 34, 516
TIME - 1931 N8473C PX- 0 0 0 PLEASURE/PERSONAL TRANSP TOTAL HOURS, 207 IN TYPE,
                             N84/3C PX- 0 0 0
DAMAGE-DESTROYED OT- 0 0 0
INTENDED DESTINATION
SPOKANF WASH
                                                                                                            NOT INSTRUMENT RATED.
        DEPARTURE POINT
          HILLSBORO, OREG
                                                                       PHASE OF OPERATION
        TYPE OF ACCIDENT
           COLLISION WITH GROUND/WATER: UNCONTROLLED
                                                                          IN FLIGHT: UNCONTROLLED DESCENT
         PROBABLE CAUSE(S)
           PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS
            PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT
        FACTOR(S)
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
            MISCELLANEOUS ACTS, CONDITIONS - AIRFRAME ICE
            WEATHER - LOW CEILING
WEATHER - ICING CONDITIONS-INCLUDES SLEET, FREEZING RAIN, ETC.
        WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT
        MISSING AIRCRAFT - LATER RECOVERED
        SKY CONDITION
                                                                       CEILING AT ACCIDENT SITE
         VISIBILITY AT ACCIDENT SITE
                                                                       PRECIPITATION AT ACCIDENT SITE
        3 MILES OR LESS
OBSTRUCTIONS TO VISION AT ACCIDENT SITE
                                                                         RAIN
                                                                       TYPE OF WEATHER CONDITIONS
          FOG
                                                                          VFR
         TYPE OF FLIGHT PLAN
          FIRE AFTER IMPACT
        REMARKS- FLEW INTO KNOWN ICING COND. ACFT NOT DE-ICER EQUIPPED. RECOVERY DATE 1/12/71.
```

Full narrative is not available