## NTSB Identification: MIA71AM115

14 CFR Part 135 Scheduled operation of HANKINS AIRWA\* Aircraft: BEECH E18S, registration: N5605D

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-1008	71/6/22 TIME - 215	BIRMINGHAM,ALA 60	BEECH E18S N5605D DAMAGE-DESTROYED	PX-	0	0	0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	ATP,FLIGHT INSTR., AGE 26, 5831 TOTAL HOURS, 2557 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - BIRMINGHAM

DEPARTURE POINT INTENDED DESTINATION

MOBILE,ALA NASHVILLE,TENN

TYPE OF ACCIDENT STALL

LAST ENROUTE STOP BIRMINGHAM,ALA PHASE OF OPERATION TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
MISCELLANEOUS ACTS, CONDITIONS - CARGO SHIFTED
FIRE AFTER IMPACT REMARKS- MAIL FLT. CARGO IMPROPERLY TIED DOWN, SHIFTED TO REAR.

Full narrative is not available