

NTSB Identification: MKC74AK012

14 CFR Part 135 Nonscheduled operation of LISA-JET,INC.
 Aircraft: GATES LEAR 25, registration: N40LB

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3965	73/9/25 TIME - 0618	LINCOLN,NEBR	GATES LEAR 25 N40LB DAMAGE-DESTROYED	CR- PX- OT-	2 1 0	0 0 0	COMMERCIAL AIR TAXI-PASSG	AIRLINE TRANSPORT, AGE 44, 2690 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - LINCOLN MUNI DEPARTURE POINT INTENDED DESTINATION LINCOLN,NEBR OMAHA,NEBR TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: UNCONTROLLED TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING MISCELLANEOUS ACTS,CONDITIONS - CREW COORDINATION-POOR FACTOR(S) WEATHER - LOW CEILING WEATHER - FOG WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE OBSCURATION 100 VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 1/2 MILE OR LESS NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE TEMPERATURE-F FOG 56 WIND DIRECTION-DEGREES WIND VELOCITY-KNOTS 140 3 TYPE OF WEATHER CONDITIONS TYPE OF FLIGHT PLAN IFR IFR REMARKS- PLT RATED IN MODEL PREVIOUS DAY.								

Full narrative is not available