

NTSB Identification: FTW74AF017

14 CFR Part 135 Nonscheduled operation of ROBERT AIRWAYS  
Aircraft: BEECH E18S, registration: N50JR

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3541	73/9/20	NATCHITOCHES,LA	BEECH E18S	CR-	1	0	0	COMMERCIAL	AIRLINE TRANSPORT, AGE 57, 14290 TOTAL HOURS, 2190 IN TYPE, INSTRUMENT RATED.
	TIME - 2245		N50JR	PX-	5	0	0	AIR TAXI-PASSG	
			DAMAGE-DESTROYED	OT-	0	0	0		
NAME OF AIRPORT - NATCHITOCHES MUNI									
DEPARTURE POINT		INTENDED DESTINATION			LAST ENROUTE STOP				
NATCHITOCHES,LA		DALLAS,TEX			SHERMAN,TEX				
TYPE OF ACCIDENT		PHASE OF OPERATION							
COLLIDED WITH: TREES		TAKEOFF: INITIAL CLIMB							
PROBABLE CAUSE(S)									
PILOT IN COMMAND - FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS									
FACTOR(S)									
PILOT IN COMMAND - PHYSICAL IMPAIRMENT									
WEATHER - FOG									
WEATHER - OBSTRUCTIONS TO VISION									
TERRAIN - HIGH OBSTRUCTIONS									
SKY CONDITION				CEILING AT ACCIDENT SITE					
CLEAR				UNLIMITED					
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE					
5 OR OVER(UNLIMITED)				NONE					
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F					
HAZE				69					
WIND VELOCITY-KNOTS				TYPE OF WEATHER CONDITIONS					
CALM				VFR					
TYPE OF FLIGHT PLAN									
NONE									
REMARKS- PLT HAD SEV CORONARY ARTERY DISEASE.RAN FRM MOTEL TO NEAR ARPT,ABT 3MI.									

Full narrative is not available